

Sample size code letters

General inspection levels

Lot or batch size			I	II	III
2	to	8	A	A	B
9	to	15	A	P	C
16	to	25	B	C	D
26	to	50	C	D	E
51	to	90	C	E	F
91	to	150	D	F	G
151	to	280	E	G	H
281	to	500	F	H	J
501	to	1200	G	J	K
1201	to	3200	H	K	L
3201	to	10000	J	L	M
10001	to	35000	K	M	N
35001	to	150000	L	N	P
150001	to	500000	M	P	Q
500001	and	over	N	Q	R